

10082207.022632




Fig.1(Prior Art)

scanning direction




Fig.2(Prior Art)

2002220 40228001




Fig.3a(Prior Art)




Fig.3b(Prior Art)




Fig.4a(Prior Art)




Fig.4b(Prior Art)




Fig.4c(Prior Art)




Fig.5




Fig.6

200220 402200T
1002207 502200
200220 402200T




Fig.7







Fig.8






Fig.10a




Fig.10b




Fig.10c




Fig.11a




Fig.11b




Fig.11c

20220740330001




Fig.12a




Fig.12b




Fig.12c

2025-09-24 10:22:00